



Repair Part Sheet


BMS-308 Cylinder

Form No. BMS308RP Rev. B Date: 20.05.2015



BELIUM Cylinders should be repaired only by a qualified operator or Authorized BELIUM Service Centers. Use Only BELIUM or other approved hydraulic oil. Release pressure in hydraulic system and disconnect hose(s) before making repair.

Parts List



Item No.7: Torque to 22-44 ft. lbs.
[30-60 Nm].

Item No.17: Torque to 22-44 ft. lbs.
[30-60 Nm].

Item No.6: Torque to 22-44 ft. lbs.
[30-60 Nm].

Apply Teflon tape or Loctite 545
thread sealant. Leave first complete
thread free to prevent tape particles

Item No.	Part Number	Description	Quantity
1	SG252G	Saddle	1
2	BMS251-4	Thread Cover	1
3★	21689	Wiper Ring	1
4	21460	Anti-wear Ring	2
5	BMS308-1	Cylinder	1
6	BAC-201A	Coupler	1
7	11008	Bolt	1
8★	QY2-13	Copper Washer	2
9	BMS308-2Y	Piston	1
10	31049	Spring Assembly	1
11	21661	Anti-wear Ring	1
12★	21422	Gasket	1
13★	24349	Y-ring	1
14★	24070	O-ring	1
15★	21340	Gasket	1
16	BMS308-3Y	Base	1
17	11012	Bolt	1

★ Items included in Repair Kit, Repair Kit order number: **BMS308-RP-B**